Channel Mitigation Monitoring Sheets I, II, III, AND IV

Monitoring Data Record

Project Title: R-2239C Site 1 (US-421 Site 1)	COE Action ID: 199920833							
Project Title: R-2239C Site 1 (US-421 Site 1) Stream Name: City, County and other Location Information: US 42	DWQ Number: 990492							
City, County and other Location Information: US 42	1 Near I-77 in Wilkes / Yadkin Co.							
Date Construction Completed:	Monitoring Year: (1) of 1							
Date Construction Completed: Ecoregion: 8 digit F	HUC unit 03040101							
USGS Quad Name and Coordinates:								
Rosgen Classification:								
Rosgen Classification: Length of Project: Urban or Rural: Rural Watershed Size:								
Monitoring DATA collected by: M. Green, D. Jenkins Date: 5/17/05								
Applicant Information:								
Name: NCDOT Roadside Environmental Unit								
Address: 1425 Rock Quarry Rd. Raleigh, NC 27610								
Telephone Number: (919) 861-3772 Email address:								
Consultant Information:								
Name:								
Address:	Address:							
Telephone Number:								
Project Status: Complete								
Monitoring Level required by COE and DWQ (40-								
Monitoring Level 1 requires completion of Section 1	, Section 2 and Section 3							
Section 1. PHOTO REFERENCE SITES (Monitoring at all levels must complete this section) Attach site map showing the location and ang designation (name, number, letter, etc.) assigned to experience be provided for all structures and cross section location upstream and downstream view. Photos taken to document vegetation should blocations). Attach photos and a description of each rethe use of a photo identification board in each photo. Total number of reference photo locations at this states.	ach reference photo location. Photos should ons, should show both banks and include an ument physical stability should be taken in be taken in summer (at representative eference photo or location. We recommend to identify location.							
Individual from whom additional photos can be obtained (name, address, phone):								
Other Information relative to site photo reference:								
If required to complete Level 3 monitoring <u>only</u> stop here; otherwise, complete section 2.								

Section 2. PLANT SURVIVAL Attach plan sheet indicating reference photos. Identify specific problem areas (missing, stressed, damaged or dead plantings): Estimated causes, and proposed/required remedial action: ADDITIONAL COMMENTS: This is the 4th quarter of monitoring and there are no problems at this time. Stream is highly vegetated with various thick grasses and black willow. NCDOT has completed one year of quarterly monitoring and is requesting to discontinue visual inspection of vegetation at this site.

If required to complete Level 1 and Level 2 monitoring only stop here; otherwise, complete section 3.

Section 3. CHANNEL STABILITY

Visual Inspection: The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. <u>Physical measurements of channel stability/morphology will not be required.</u> Include a discussion of any deviations from as-built and an evaluation of the significance of these deviations and whether they are indicative of a stabilizing or destabilizing situation.

The stream is stable and is doing well for the 4th quarter of monitoring. NCDOT has completed one year
of quarterly monitoring and is requesting to discontinue visual inspection of channel stability at this site.

Date	Station	Station	Station	Station	Station
Inspected	Number	Number	Number	Number	Number
Structure					
Type					
Is water					
piping					
through or					
around					
structure?					
Head cut or					
down cut					
present?					
Bank or scour					
erosion					
present?					
Other					
problems					
noted?					

NOTE: Attach separate narrative sheets to each monitoring report describing/discussing the overall monitoring results. Include the identification of specific problem areas/channel failures, estimated cause and proposed/required remedial action. This should include a brief discussion of any parameter that has changed significantly from asbuilt.

US 421 Site 1





Photo 1 Photo 2